

**Pergam Technical Services, Inc.**  
**SELMA**  
**Inspection Report**

MPB6

Customer:  
Test

Inspection Date: 15.05.2015

Inspection area:  
Renton, WA

Operators:  
SELMA Expert

File: trak\_150515\_001

Start Time:10:47:18.31  
Finish Time:10:50:32.71


Total Distance: 0.571 km

Weather conditions:  
ok

Signal at Start: 4665  
Signal at Finish: 4649

Data file: trak\_150515\_001

Main map:



Data file: trak\_150515\_001

Gas detection table:

<b>Detection</b>	<b>Time</b>	<b>Latitude</b>	<b>Longitude</b>	<b>Maximal vechicle speed, km/h</b>	<b>Maximal gas concentration, ppm</b>
1	10:48:32.91	47.4419200	-122.2204400	13.6	1027.17

Data file: trak\_150515\_001

Gas detection:

Detection	Time	Latitude	Longitude	Maximal vehicle speed, km/h	Maximal gas concentration, ppm
1	10:48:32.91	47.4419200	-122.2204400	13.6	1027.17

Map:

